R4-C INSTRUCTION MANUAL

ERRATA SHEET
S/N 21000 TO 25900

Figure 4-1., page 4-3
Table 5-3., page 5-5
Figure 5-3., page 5-9

Q13 is a 2N3563 instead of 2N3858. (PTO)

Figure 5-3., page 5-9

C44 & C40 are both .005 uF.

C191 is a 27 pF instead of 39 pF.

C49 is a 430 pF instead of a 390 pF.

C106 is an 8.2 pF instead of 5 pF.

C119 is a 680 pF instead of 390 pF.

C153 is a 75 pF instead of 90 pF (PTO)

C155 is selected in production (PTO).

C157 is two (2) 45 pF tubulars in parallel (PTO).

C160 is a 12 pF instead of 10 pF (PTO).

R5 is a 1.5K instead of 470 Ohm.

R105 is a 100 Ohm instead of 560 Ohm (PTO).

R108 is a 330 Ohm instead of 100 Ohm (PTO).